



COUNTY OF PRINCE WILLIAM

Fire Marshal's Office

5 County Complex Court, Suite 160, Prince William, Virginia 22192
(703) 792-6360 Metro 631-1703, Ext. 6360, Fax (703) 792-6492-7691

DEPARTMENT OF
FIRE & RESCUE

Kevin J. McGee
Chief

March 24, 2016

Mr. Uriah Kiser
Publisher
PotomacLocal.com

Subject: Freedom of Information Act (FOIA)
Fire Incident Report #16031800010546
Incident Address: 8105 Spruce St.
Incident Date: 3-18-16

Dear Sir:

The Office of the Fire Marshal (OFM), a law enforcement office, has received your request for a copy of the fire incident report referenced above. We have attached a copy of that report per your request. However, within the summary information provided to you at the discretion of the OFM, the County redacts social security numbers, personal contact information, and birth date information of third parties.

If you have any questions related to this response, please do not hesitate to contact our office at 703-792-6360.

Very truly yours,

Captain Brian Ferguson
Fire Marshal

Prince William County Department of Fire & Rescue

Incident-Detail_New

Incident #: FD16031800010546

CAD Incident Information:

Cad Incident Number:	FD16031800010546	First Due:	508
Agency:	FD	Box:	050805
Entry Date:	03/18/2016 01:26:12	Source:	9
Close Date:	03/18/2016 10:06:27	Mod. Circumstance:	HOUSE
Init Code:	STRUCT	Final Code:	STRUCT
Description:	STRUCTURE FIRE	Dispo:	CN
Priority:	2	E911 Date:	03/18/2016 01:24:44
Location:	8105 SPRUCE ST	All Dispo:	CN, AS, EX

Incident Comments Report:

Comment Date	User Id	Device Name	Comment(s)
03/18/2016 01:26:12	dmb6500a	PSCCCT06	HOUSE CLOSE TO ABOVE LOC // SOMETHING CATCHING ON FIRE // SEE SMOKE AND FLAMES //
03/18/2016 01:26:12	SYSTEM	SystemDevice	Manassas/Manassas Park BC: Dispatch a MNSS/MNPK BC if MNSS/MNPK units are responding to any STRUCTURE FIRE in PWC[Agency/IRF]
03/18/2016 01:26:49	dmb6500a	PSCCCT06	CALLER CHECKING TO SEE IF ANYONE IS HOME BY KNOCKING HOME
03/18/2016 01:26:58	dmb6500a	PSCCCT06	*KNOCKING ON DOOR
03/18/2016 01:28:01	dmb6500a	PSCCCT06	CALLER STATING IT LOOKS LIKE ITS GETTING WORSE
03/18/2016 01:28:12	kmg6500a	PSCCWEST	SSD 408A
03/18/2016 01:28:35	dmb6500a	PSCCCT06	**CORRECTION CALLER IS STATING THAT 8105 MAPLEWOOD DR***
03/18/2016 01:28:58	dmb6500a	PSCCCT06	NOT SURE WHAT IS ON FIRE
03/18/2016 01:29:03	mmb5769	PSCCF3	C508
03/18/2016 01:29:11	smr6500a	PSCCCT11	Dup: ANOTHER CALLER STATES HOUSE IS ON SPRUCE ST JUST BEHIND CALLER'S HOUSE 8106 MAPLEWOOD
03/18/2016 01:29:20	dmb6500a	PSCCCT06	**CALLER NOT SURE IF ANYONE IS IN HOME**
03/18/2016 01:29:50	smr6500a	PSCCCT11	MY CALLER STATED HE THINKS A FAMILY LIVES THERE BUT UNK IF ANYONE THERE
03/18/2016 01:29:57	smr6500a	PSCCCT11	HOUSE BECOMING FULLY INVOLVED
03/18/2016 01:30:05	kmg6500a	PSCCWEST	CORRECTION ** HOUSE ON FIRE , ON SPRUCE STREET // 8105 SPRUCE
03/18/2016 01:30:14	SYSTEM	SystemDevice	Manassas/Manassas Park BC: Dispatch a MNSS/MNPK BC if MNSS/MNPK units are responding to any STRUCTURE FIRE in PWC[Agency/IRF]
03/18/2016 01:30:58	mmb5769	PSCCF3	1 STORY A B SIDE NEXT ENG REVERSE LAY 2 HOUSE DOWN ON MAPLEWOOD PULLED 3/4 PULLING WALKING AROUND

03/18/2016 01:32:15	mmb5769	PSCCF3	1 STORY WITH BASEMENT HEAVY FIRE 1ST FLOOR EXT TO ATTIC TRANSITIONAL ATTACK TRYING ENTRY FOR ATTACK AND SEARCH
03/18/2016 01:33:30	kmg6500a	PSCCWEST	<Incid #:PD16031800065596 Location: 8105 SPRUCE ST(8106 MAPLEWOOD DR)>
03/18/2016 01:33:59	mmb5769	PSCCF3	BC582 DIV A
03/18/2016 01:35:24	mmb5769	PSCCF3	E508 READY FOR WATER
03/18/2016 01:36:39	mmb5769	PSCCF3	E508 TO BASEMENT DOOR NOW
03/18/2016 01:37:40	mmb5769	PSCCF3	TW RES IN SEARCH GAS SECURED NEED 2ND LINE
03/18/2016 01:37:57	mmb5769	PSCCF3	FIRE GROWING ON C SIDE
03/18/2016 01:38:16	mmb5769	PSCCF3	FIRE KNOCKED DOWN ON FIRST FLOOR IN HALLWAY SEARCHING HALLWAY NEED LIEN TO BASEMENT
03/18/2016 01:38:24	mmb5769	PSCCF3	E508 ORDERED NOT TO GO TO BASEMENT
03/18/2016 01:38:32	mmb5769	PSCCF3	ASKING FOR 2ND LINE FOR BASEMENT TO MAKE SURE
03/18/2016 01:38:47	mmb5769	PSCCF3	E501 HOSE BURNING THROUGH
03/18/2016 01:39:00	mmb5769	PSCCF3	DIV A REQ E 508 BACKING OUT SIDE A
03/18/2016 01:39:07	mmb5769	PSCCF3	E511 SEC WATER FROM 8102
03/18/2016 01:40:14	mmb5769	PSCCF3	COM DIRECT 20MINS IN
03/18/2016 01:40:36	mmb5769	PSCCF3	T438 ENR DOES HE STILL WANT T523
03/18/2016 01:40:53	mmb5769	PSCCF3	DIV A ... UNK ACCOUNTABILITY OF OCC
03/18/2016 01:41:11	mmb5769	PSCCF3	DIV A E508 E501 TW501 R501 NEED ANOTHER
03/18/2016 01:41:23	mmb5769	PSCCF3	E516 COMING TO DIV A
03/18/2016 01:42:28	tsamuels	PSCCUFRO	BC591 NOTIFIED
03/18/2016 01:42:32	T523	FDMD0092	DISPO CN:PUT IN SERICE
03/18/2016 01:43:24	mmb5769	PSCCF3	DIV A STILL DOING PERIMETER SEARCH
03/18/2016 01:44:28	rsaikowski	PSCCLT	CHIEF MCGEE AND MCCLINTOCK NOTIFIED
03/18/2016 01:45:19	mmb5769	PSCCF3	SING STORY OVER BASEMENT FIRE THROUGHOUT FIRE KNOCKED DOWN 1ST AND ATTIC STILL HEAVY IN BASEMENT
03/18/2016 01:45:53	smr6500a	PSCCCT11	HAVE HOMEOWNER BLUE, JOANIE _____ NO ONE IN HOME DUE TO FIRE EARLIER TODAY IS ENR FROM NEARBY HOTEL IN RED MINIVAN
03/18/2016 01:46:29	mmb5769	PSCCF3	REQ NOVEC AND FM
03/18/2016 01:46:59	kmg6500a	PSCCWEST	SSD 408A
03/18/2016 01:47:22	jdb6500a	PSCCF1	FM515 DIRECT //
03/18/2016 01:47:35	mmb5769	PSCCF3	NEED TO REPLACE E508
03/18/2016 01:47:48	mmb5769	PSCCF3	SENDING E511
03/18/2016 01:48:06	kxa6810a	PSCCF2	NOVEC - JOSH NOTIFIED - ETA 1HR

03/18/2016 01:48:16	jdb6500a	PSCCF1	1 HR ETA FOR NOVEC
03/18/2016 01:48:57	mmb5769	PSCCF3	A LOT OF HEAT FROM BASEMENT
03/18/2016 01:50:09	mmb5769	PSCCF3	E501 NEEDS AIR DIV A GOOD ON UNITS
03/18/2016 01:50:32	mmb5769	PSCCF3	E508 TO REHAB DRIVER SHUT DOWN BLUE LINE
03/18/2016 01:53:20	mmb5769	PSCCF3	R501 IN BASEMENT GOOD KNOCK DOING PRIMARY WORKING TO CD SIDE BULK OF FIRE KNOCKED DOWN MULTI HOTSPOTS
03/18/2016 01:54:29	mmb5769	PSCCF3	FIRE FLARE BACK UP ON ROOF PER CMD
03/18/2016 01:54:46	mmb5769	PSCCF3	LITTLE SPOT FIRES PER DIV A E511 WILL HANDLE PRIMARY ON 1ST FLR COMPLETE
03/18/2016 01:55:23	mmb5769	PSCCF3	TW501 F TO F FRONT DOOR
03/18/2016 01:57:36	mmb5769	PSCCF3	FE501 E501 TW501 E516 E511 R501 DIV A
03/18/2016 02:00:19	mmb5769	PSCCF3	REQ MED
03/18/2016 02:00:24	mmb5769	PSCCF3	CREW OF FE 501
03/18/2016 02:00:39	mmb5769	PSCCF3	M508 WILL TRANSPORT
03/18/2016 02:01:20	mmb5769	PSCCF3	E508 RESP TO DIV A
03/18/2016 02:01:56	mmb5769	PSCCF3	R501 IN BASEMENT AT PANEL TRYING TO GET MAIN BREAKER THINKS THERE MULTIPLE BREAKERS
03/18/2016 02:02:36	mmb5769	PSCCF3	TW501 FIRE THROUGH ROOF SIDE C
03/18/2016 02:02:42	mmb5769	PSCCF3	E516 GOING TO PUT OUT
03/18/2016 02:04:21	mmb5769	PSCCF3	REQ RED CROSS
03/18/2016 02:04:27	mmb5769	PSCCF3	7 OCC NO PETS
03/18/2016 02:04:59	mmb5769	PSCCF3	M509 TO COME DOWN SPRUCE
03/18/2016 02:06:05	mmb5769	PSCCF3	DIV A IS GOING TO KNOCK OPEN JUST ABOVE R501 CREW
03/18/2016 02:06:15	mmb5769	PSCCF3	DIV A ABV E516
03/18/2016 02:06:56	mmb5769	PSCCF3	REQ BLDG INSP
03/18/2016 02:07:49	mmb5769	PSCCF3	REQ 2 ENG
03/18/2016 02:08:46	mmb5769	PSCCF3	R501 PRIMARY NEG
03/18/2016 02:09:00	mmb5769	PSCCF3	DIV A PRIMARY BASEMENT FIRST FLOOR NEG
03/18/2016 02:09:42	rsaikowski	PSCCLT	BLDG INSPECTOR NOTIFIED, ETA 1 HOUR
03/18/2016 02:10:23	mmb5769	PSCCF3	3 ADULTS 4 CHILDREN
03/18/2016 02:10:31	mmb5769	PSCCF3	40MINS IN
03/18/2016 02:12:40	rsaikowski	PSCCLT	RED CROSS NOTIFIED
03/18/2016 02:13:12	mmb5769	PSCCF3	E511 FE501 R501 TW501 E508 E516 ONLY ONES INTERIOR E508 21ST FL DRIVER AT TRK E516 3 DRIVER AT ENG

03/18/2016 02:14:25	mmb5769	PSCCF3	POWER SEC PANEL BOX IN BASEMENT R501 THINKS BUT NOT CERTAIN
03/18/2016 02:14:43	mmb5769	PSCCF3	STILL SOME FIRE SIDE A MIDDLE OF HOUSE
03/18/2016 02:14:48	mmb5769	PSCCF3	E516 DIRECT
03/18/2016 02:20:25	mmb5769	PSCCF3	DIV A MOVING INTO OVERHAUL
03/18/2016 02:20:36	mmb5769	PSCCF3	FOR THE MOST PART EXTINGUISHED
03/18/2016 02:24:39	mmb5769	PSCCF3	NO VISUAL FIRE FROM OUTSIDE SOME RESID SMOKE FROM FRONT
03/18/2016 02:29:03	mmb5769	PSCCF3	REHAB AT M509 IN DRIVEWAY NEXT DOOR
03/18/2016 02:31:46	mmb5769	PSCCF3	DIV A E509 ONLY WORKING
03/18/2016 02:32:05	mmb5769	PSCCF3	ALL OTHERS TRANSITIONING TO REHAB OR FOR AIR
03/18/2016 02:34:04	mmb5769	PSCCF3	RED CROSS 30-40
03/18/2016 02:37:42	rsaikowski	PSCCLT	C501 NOTIFIED OF INJURY
03/18/2016 02:40:26	mmb5769	PSCCF3	NEED COLUMBIA GAS TW501 WORKING ON EXTERIOR LIGHTING
03/18/2016 02:42:14	mmb5769	PSCCF3	DIV A ALL WORKING UNITS TO REHAB
03/18/2016 02:45:19	jdb6500a	PSCCF1	COLUMBIA GAS IS DIRECT AND RESPONDING BUT NO ETA
03/18/2016 02:49:42	mmb5769	PSCCF3	FM515 20
03/18/2016 03:23:35	mmb5769	PSCCF3	NEEDS WATER AUTHORITY TO SHUT OFF WATER TO RESD
03/18/2016 03:27:00	mmb5769	PSCCF3	SENDING IN E509B TO HELP R501 STAYING OUT OF FRONT ROOM AND KITCHEN
03/18/2016 03:27:13	jdb6500a	PSCCF1	PWC WATER AUTH NOTIFIED // RESPONDING ASAP // NO ETA
03/18/2016 03:33:40	mmb5769	PSCCF3	TW501 COLUMBIA GAS NEG ON TAKING METER
03/18/2016 03:51:28	kmg6500a	PSCCWEST	FM515 ENR TO STATION 501
03/18/2016 03:53:45	mmb5769	PSCCF3	E508 WILL BE CONTACT
03/18/2016 03:54:41	mmb5769	PSCCF3	TERM COMM AND 5D

Case Number(s):

Report Number	Agency	Callsign	Inserted Timestamp
FD160007951	FD	M508	03/18/2016 01:26:51
MNPK160000392	MNPK	E509B	03/18/2016 01:26:51
MNSS160001233	MNSS	BC582	03/18/2016 01:26:51

Disposition(s):

Unit	Disposition Code	Disposition Date	Comments
T523	CN	03/18/2016 01:42:31	PUT IN SERICE
E506	AS	03/18/2016 03:08:54	
E508	EX	03/18/2016 07:30:38	

Unit(s) Assigned:

Unit	Assigned	Enroute	Arrived	Clear
R508	03/18/2016 01:26:46			03/18/2016 04:00:27
T511	03/18/2016 01:26:46			03/18/2016 04:00:39
5D	03/18/2016 01:26:46			03/18/2016 06:14:33
5E	03/18/2016 01:26:46			03/18/2016 06:14:39
5F	03/18/2016 01:26:46			03/18/2016 06:14:44
5G	03/18/2016 01:26:46			03/18/2016 06:14:50
E508	03/18/2016 01:26:46		03/18/2016 01:32:09	03/18/2016 07:30:38
FE501	03/18/2016 01:26:46	03/18/2016 01:27:57	03/18/2016 01:32:24	03/18/2016 04:00:12
E509B	03/18/2016 01:26:46	03/18/2016 01:28:00	03/18/2016 01:32:51	03/18/2016 03:56:10
TW501	03/18/2016 01:26:46	03/18/2016 01:28:24	03/18/2016 01:32:28	03/18/2016 03:59:50
R501	03/18/2016 01:26:46	03/18/2016 01:28:30	03/18/2016 01:33:26	03/18/2016 03:56:32
M508	03/18/2016 01:26:46	03/18/2016 01:28:31	03/18/2016 01:34:08	03/18/2016 02:27:50
E511	03/18/2016 01:26:46	03/18/2016 01:29:17	03/18/2016 01:39:25	03/18/2016 03:57:53
BC582	03/18/2016 01:26:46	03/18/2016 01:29:58	03/18/2016 01:33:23	03/18/2016 04:00:02
E516	03/18/2016 01:26:46	03/18/2016 01:32:45	03/18/2016 01:37:30	03/18/2016 03:54:49
BC501Y	03/18/2016 01:26:46	03/18/2016 01:35:04	03/18/2016 01:37:11	03/18/2016 02:04:14
T523	03/18/2016 01:30:24	03/18/2016 01:32:39		03/18/2016 01:42:31
C508	03/18/2016 01:31:28			03/18/2016 04:05:18
T438	03/18/2016 01:37:18	03/18/2016 01:37:29		
BC403	03/18/2016 01:39:45			
M509	03/18/2016 02:00:23	03/18/2016 02:01:56	03/18/2016 02:06:20	03/18/2016 03:54:12
E507B	03/18/2016 02:08:14	03/18/2016 02:10:47	03/18/2016 02:20:14	03/18/2016 03:42:45
E506	03/18/2016 02:08:14	03/18/2016 02:12:34	03/18/2016 02:24:08	03/18/2016 03:08:54
BC591	03/18/2016 02:13:57		03/18/2016 02:14:31	03/18/2016 03:58:27
FM503	03/18/2016 02:31:37	03/18/2016 02:31:52	03/18/2016 02:58:28	03/18/2016 07:35:19
FM515	03/18/2016 02:40:50	03/18/2016 02:40:55	03/18/2016 03:09:07	03/18/2016 05:03:09
FM521	03/18/2016 03:16:21		03/18/2016 03:16:21	03/18/2016 07:20:39
FM528	03/18/2016 04:52:42	03/18/2016 04:52:53	03/18/2016 04:52:42	03/18/2016 10:06:27